

7/5/24 – 4:00 p.m.

South Audubon Avenue and West Swann Avenue

Water covering all inlets and coming out

**(This is 2 hours after the rain and most people I
talked to did not know it had rained)**



7/5/24 – 4:00 p.m.

**From lack of storm water capacity, all inlets at
the intersection of West Fountain Boulevard and
South Audubon Avenue are underwater and
pushing water out
(This is 2 hours after the rain)**



7/5/24 – 4:00 p.m.

Water running down both sides of South Lakeview Road from West and East Bristol Avenue, West Edgewood Road and South Lakeview Road from West Morrison North to West Parkland Boulevard. This water comes from elevation 20 and pushes the water out of the inlets at South Audubon Avenue at elevation 16 (This is 2 hours after the rain)



7/5/24 – 4:00 p.m.

**Water flows west on West Bristol Avenue from 100' west of South Howard Avenue to South Lakeview Road. This overflows the inlets on Lakeview Road. The water then runs north to West Parkland Boulevard which increases the flooding on West Fountain Boulevard, South Audubon Avenue and West Swann Avenue
(This is 2 hours after the rain)**

